Work Order ID 55440

January 19, 2010 7:45:18 AM

Item ID:

D120-639-011

Accept



Setup Start

Stop



Revision ID:

Item Name:

Tungsten Carbide Wearplate

Start Date:

Required Date: 1/19/10

1/19/10

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

QC:

Date: Date: **Tooling:**

0.00

SPC (Y/N):

Date: Date:

Stop

Start

Sequence ID/ Work Center ID Operation Description

Set Up/ **Run Hours**

Draw Number Draw Rev.

Plan Accept Code Qty

Reject Qty

Run

Reject Number

Insp. Stamp

Draw Nbr

Revision Nbr

Pick Kit

DSI 9223

Rev A Rev A

IIN-D120-639

100

DOCUMENT CONTROL

Memo

Document Control

0.00

Photocopy bluefile and type labels per PPP D120-639-011 CHG 002

Siolalia

105

Packaging

Memo

0.00

0.00

MF 10-1-19

Packaging

Work Order ID 55440

January 19, 2010 7:45:19 AM

Item ID:

D120-639-011

Accept



Setup Start



Stop

Revision ID:

Item Name:

Tungsten Carbide Wearplate

Start Date:

1/19/10

QC:

Start Qty: 2.00

Req'd Qty: 2.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Start Run

Stop

Required Date: 1/19/10

Date:

SPC (Y/N):

Date:

Sequence ID/ **Work Center ID**

110

Quality Control

Operation Description

QC4- 100% Inspect kits for completeness

Set Up/ **Run Hours**

Draw Number Draw Rev.

Plan Code

Accept **Qty**

Reject Qty

Reject Number

Insp. Stamp

Memo

0.00

0.00

0.00

120

Packaging Packaging

Packaging

0.00 Memo

Package and Identify as per PPP D120-639-011

130

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/01/1998 MF 10-1-19

· Picklist Print

January 19, 2010 7:45:16 AM

Work Order ID: 55440

Parent Item:

D120-639-011

Parent Item Name: Tungsten Carbide Wearplate

Comments:

02.09.13 Re-format, Added MS27130-S30

ΚJ

Start Date: 1/19/10

Required Date: 1/19/10

Start Otv: 2.00

Required Oty: 2.00

				527150 050	143			_	Aure Qey. 2.00	•	required Qij. 2	.00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2746 }		Manufactured	No			105	Each	16.0000	2.0000	0-1-1	9 Sy)

_			<u>Warehouse</u>	Lo	oc Qty	Loc Code			
			Location						
			Main Warehouse						
D2656-31. Wearshoe	Manufactured	No	ST 43599 46960	105	16 2 14 Each	6.0000	2.0000	10-1-19	Syl
			Warehouse	Lo	e Otv	Loc Code			1

Wearshoe								10-1-19	5
4			<u>Warehouse</u>	<u>Lo</u>	oc Qty	Loc Code			/
			Location Main Warehouse						
5			ST 44119		6 6			2	
D2656-13	Manufactured	No		105	Each	8.0000	2.0000	10-1-19	SU

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
ST	8		
(44158)	8		2
\ /			

Picklist Print

January 19, 2010 7:45:17 AM

Work Order ID: 55440

Parent Item:

D120-639-011



Parent Item Name: Tungsten Carbide Wearplate

Comments:

IPP

02.09.13 Re-format, Added MS27130-S30

ΚJ

Start Date: 1/19/10

Required Date: 1/19/10

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Primary Item Location Last Location Route Seq ID

Unit of Measure

Oty on Hand

Remaining Qty Qty To Pick Issued Date Issued

Status

ALS7-1032-130 / 136

Purchased

No

105

Each

1,254.000 72.0000

10-1-19 5

S Ins.
Insert

		Warehouse	Lo	e Qty	Loc Code		
		Location					
		Main Warehouse					
		ST		1254			
		(105 <u>855</u>)		6			_6
		108606		52			
		111529		130			
		111779		135			
		112772		11			
		113238		920			_ (0 ()
anufactured	No		105	Each	69.0000	10.0000	

D2648-3 Wearpad

Ma

Warehouse	Loc Qty	Loc Code	
Location			
OFFSHORE			
FG	12		
45316	12		
Main Warehouse			
FP17	47		
52516	47		
Main Warehouse			
ST	10		
46957	10		

January 19, 2010 7:45:17 AM

Work Order ID: 55440

Parent Item:

D120-639-011

Parent Item Name:

Tungsten Carbide Wearplate

Comments:

02.09.13 Re-format, Added MS27130-S30

ΚJ

Start Date: 1/19/10

Required Date: 1/19/10

Start Qty: 2.00

Required Qty: 2.00

Component Item	ID/
Item Name	
MS27020 1 08	

Replacement Mfg/ Item ID

Purch

Primary Item Location

Warehouse

Warehouse

Last Location

Route Seq ID

Unit of Measure

Qty on Hand

Loc Code

Loc Code

Loc Code

Remaining Qty To Pick

Qty Issued

Date Issued

Status

Purchased

No

105

Each

40 2,792.000 80.0000

10-1-1959

	Screw
,	

Alnsert

AN960JDIOL TOC

Purchased

No

Location	
Main Warehouse	
ST	2792
110467	112
(110552)	680
110835	2000

105 Each

Loc Qty

Loc Qty

4,295.000 80.0000



10-1-19 50



- 1 1961 411 401101 410 10110 41111 53110 61110 1001 11011 24113
Washer

MS27130-S30 Purchased No

Location Main Warehouse ST 101291 105793 110985

4× 267.0000 8.0000

10-1-19.5f (20)

Warehouse Location

Main Warehouse

100154

267 267

Loc Qty

ICA Page 19 (20 blank) of 20

REFERENCE ONLY

32.2 WEIGHT AND BALANCE

The following weight and balance information is for the Dart wearplate kits that are being installed. The weight and balance of any wearplates that are being removed from the aircraft is the responsibility of the installer.

Installation	Weight	LAT	ERAL	LONGITUDINAL		
ilistaliation	Weight	Arm	Moment	Arm	Moment	
D120-639-011	3.1 lb	136.0 in	422 in lb	±40.7 in	±126 in lb	
TUNGSTEN CARBIDE WEARPLATE KIT	1.4 kg	3.45 m	4.8 m kg	±1.04 m	±1.5 m kg	
D120-639-013	4.1 lb	136.0 in	558 in lb	±40.7 in ±1.04 m	±167 in lb	
SURFACITE TM WEARPLATE KIT	1.8 kg	3.45 m	6.2 m kg		±1.9 m kg	

32.4 PARTS LIST

⟨Qtỳ ⟨-011⟩	Qty -013	Part Number	Description
X		D120-639-011	TUNGSTEN CARBIDE WEARPLATE KIT
	Х	D120-639-013	SURFACITE [™] WEARPLATE KIT
*** .			
1 (1	,'D2746	WEARPLATE
1,	1	D2656-31	WEARPLATE
[©] 1	1	D2656-13	WEARPLATE
ζ. 5		D2648-3	WEARPAD
	5	D2648-7	WEARPAD
40	40	ALS7-1032-130	INSERT
ŀ		or AKS7-1032-130	
		or ALS4-1032-130	
		or AKS4-1032-130	
40 :	40	MS27039-1-08	SCREW
40	40	AN960JD10L	WASHER



	DESIGN	+	DRAWN BY	DART AEROSPA HAWKESBURY, ONTARIO,	
	CHECKED	A .	APPROVED	DRAWING NO.	REV. A
		_	#	DSI 9223	SHEET 1 OF 1
	DATE			TITLE	SCALE
_	01.11.	19		WEARPLATE INSERTS	NTS
	A		01.11.19	NEW ISSUE	

DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D120-639 Rev. A

REF. CANADIAN STC SH01-25 FAA STC: SR01347NY EFERENCE ONLY


REPLACE (4) AFTMOST ALS7-1032-130 INSERTS WITH (4) RNS1032-330 / MS27130-S30 INSERTS. UPDATE PARTS LIST AS FOLLOWS:


REPLACE:

QTY -011	QTY -013	Part Number	Description
40	40	ALS7-1032-130	INSERT

WITH:

QTY -011	QTY -013	Part Number	Description
∖36_	36	ALS7-1032-130	INSERT
4	4	RNS1032-330 or MS27130-S30	INSERT





Copyright @ 2001 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.